Oil Field Environmental Incident Summary

Date/Time of Notice: 05/07/2014 09:23 Responsible Party: DENBURY ONSHORE, LLC Well Operator: DENBURY ONSHORE, LLC Well Name: TRMU 44X-15H Field Name: T. R. Well File #: 16870 Date Incident: 5/6/2014 Time Incident: 11:30 Facility ID Number: **BILLINGS** Twp: 141 Rna: 101 Sec: 15 Qtr: County: Location Description: Submitted By: Mark VanGrinsven Received By: Contact Person: Mark VanGrinsven 5320 LEGACY DR PLANO, TX 75024-3127 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil 3 Mile Distance Nearest Occupied Building: Distance Nearest Water Well: 2 Mile Type of Incident: Tank Leak Release Contained in Dike: Yes - Within Dike Reported to NRC: No Spilled Units Recovered Units Followup **Units** 3 3 Oil Barrels **Barrels Brine** Other **Description of Other Released Contaminant:** Inspected: Written Report Received: Clean Up Concluded: Risk Evaluation: none Areal Extent:

Incident: 20140507092355

Potential Environmental Impacts:

none

Action Taken or Planned:

A vac truck was dispatched and the hole was temporarily plugged while fluids were removed from the tank. Fluids were recovered by vac truck and contaminated soils will be removed

Wastes Disposal Location: C0ontractor will dispose

Agencies Involved:

Updates

Date: 5/7/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from a tank leak remained on location within the diking, according to the report. NDIC retains oversight.